



CAPABILITIES

2021

BELL 206/OH-58/407

PART#	DESC.	O/H\$	EXCH\$*
41103650-009	SERVO CYL.	1800.00	2100.00
41103750-017	SERVO CYL.	1800.00	2100.00
206-076-031-013 41000670-005	SERVO CYL.	1800.00	2100.00
206-076-031-015 41103730-005	SERVO CYL.	1800.00	2100.00
206-076-031-017 42c42641, 42c42641-1	SERVO CYL.	1800.00	2100.00
206-076-031-021 41000670-007	SERVO CYL.	1800.00	2100.00
206-076-031-023 42c42641-3	SERVO CYL.	1800.00	2100.00
206-076-031-105 41103730-007	SERVO CYL.	1800.00	2100.00
206-076-031-107 41000670-009	SERVO CYL.	1800.00	2100.00
206-076-031-109 42c42641-9	SERVO CYL.	1800.00	2100.00
206-076-022-005 RR24050, 014544-200, 014544-300	PUMP	1000.00	1300.00
206-076-022-101 850500, 850500-101	PUMP	1000.00	1300.00
206-076-030-ALL AP09V-1, -01, -03, -04, -05	PUMP	1100.00	1400.00
206-076-015-003	VALVE	500.00	750.00
206-076-034-ALL	FILTER	500.00	750.00
206-076-047-001	BRAKE M/C	1100.00	-----
206-076-062-003/101 42C42642-1, -101	SERVO	2100.00	2400.00
206-076-062-001/-005/-103 41001520-005, -007, -009	SERVO	2100.00	2400.00
206-076-062-105/125/111 41011300-101,-105,-103	SERVO	2100.00	2400.00
206-076-062-107/127 41011400-101,-103	SERVO	2100.00	2400.00

NOTES: (*) ALL EXCHANGES ARE SUBJECT TO BILLBACK

BY COMBINING QUICK TURNTIMES AND COMPETITIVE PRICING WITH HIGH QUALITY, FASCO HAS AGAIN EMERGED AS THE LEADER IN THIS COMPETITIVE FIELD

BELL 212/412

PART#	DESC.	O/H\$	EXCH\$*
212-076-004-003 41000570-001	SERVO CYL.	1900.00	2200.00
212-076-004-005 41000570-005	SERVO CYL.	1900.00	2200.00
212-076-004-101 41000570-007	SERVO CYL.	1900.00	2200.00
212-076-005-007 41000470-005	SERVO CYL.	4300.00	4900.00
212-076-005-011 41000470-011	SERVO CYL.	4300.00	4900.00
212-076-005-101 41000470-013	SERVO CYL.	4300.00	4900.00
212-076-005-111 41000470-105	SERVO CYL.	4300.00	4900.00
212-076-015-001 41000720	CHECK VALVE	600.00	850.00
SGT520-5 (204-010-937-009)	DAMPER	750.00	1000.00
204-031-920-003	DAMPER	650.00	900.00

NOTES: (*) ALL EXCHANGES ARE SUBJECT TO BILLBACK

PRICES ARE SUBJECT TO CHANGE WITHOUT NOTICE!


CALL FOR INDIVIDUAL COMPONENT REPAIR AND EXCHANGE PRICES.

**SHIPPING:
25041 Anza Drive Valencia, Ca 91355**

**BRETT FORTNER
(PRESIDENT)
EMAIL: BLF@AOL.COM
BRETT@FORTNERACCESSORY.ORG**

PH (818)548-3690 FAX (818)548-9375

**WEB SITE
WWW.FORTNERACCESSORY.ORG**



BELL 47

PART#	DESC.	O/H\$	EXCH\$*
103650-6 & -7	SERVO CYL.	975.00	1200.00
1270-3	SERVO CYL.	600.00	CALL^
1450	SERVO CYL.	600.00	CALL^
4050	VALVE ASSY.	375.00	575.00
CSC870-5	DAMPER ASSY.	550.00	750.00
A6010	HYD. PUMP	550.00	750.00
67B025	HYD. PUMP	550.00	750.00

(^) P/N 1270 & 1450 ARE NOT SUBJECT TO CORE BILLBACK UNLESS CYLINDER BARREL IS SCRAP

NOTES: (*) ALL EXCHANGES ARE SUBJECT TO BILLBACK

BELL 204/205/UH-1

PART#	DESC.	O/H\$	EXCH\$*
204-076-053-ALL	SERVO CYL	1000.00	CALL
204-076-055-ALL	IR VALVE	750.00	1000.00
SGT520-6 (204-010-937-007)	DAMPER	750.00	1000.00
204-076-052-009	SERVO CYL	SEE THE FOLLOWING	
205-076-038-007 (204-076-052-009 WITH GREASABLE BALLJOINT)	SERVO CYL.	1600.00	1900.00
205-076-099-007 (204-076-052-009 WITH NON-GREASABLE BALLJOINT)	SERVO CYL.	1600.00	1900.00
205-076-056-107 (ALT: 205-076-055-101 / 205-076-500-001)	SERVO CYL.	2200.00	2500.00

NOTES: (*) ALL EXCHANGES ARE SUBJECT TO BILLBACK

IF YOU REQUIRE SERVICE FOR AN ITEM THAT IS NOT LISTED, PLEASE CONTACT US, MOST LIKELY WE CAN DO IT